


NEW VERSION - Automatic Multiport Valve MIDAS March 2011


MODIFICATIONS:

1. **A quick-action fuse 0.4 A is added to the circuit board** on the connection of the filter pump to prevent damage to the diodes of the circuit board in case of current excess because of a bad electrical connection.
2. **Changes in the text of the electronic board**: the text MOTOR-PUMP has been replaced by the numbers 4-5.
3. **Modification of the of the automatic valve manual!**: diode specifications, maintenance of the valve and an example of connecting a standard cabinet are added.
4. **A maintenance kit has been added.** It includes three fuses and grease for lubrication of the valve shaft.
5. **The backwash press button** has been included in all automatic MIDAS valves.

CHECK NEW MANUAL:
New specifications of maintenance and electrical connection.



0.4 A Fuse



Backwash
press button